

Queue Number 2800922

Transaction Date 26 Sep 2026, 11:15:42

Site Name
840 - Emirates AuctionsTransaction Number
24790876 (CC10021) (CC10025)

Vehicle Details

Chassis Number	1J4BA2D15A*****
Specification	GCC Specification
Make	Jeep
Model	Wrangler
Model Year	2010
Color	Blue
Mileage	219449 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING RUSTY , PORTION FADED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Bumper	PORTION DENT	دعامية
01.D Fuel Tank	COVER RUSTY HOLE WEAK	خزان الوقود

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION MINOR DENT	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	REFITTED , OIL PAN DENT , PARTS GETTING RUSTY , SHAKING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition المقاعد

04.A Seat Belt	REAR RIGHT SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	FRONT RIGHT SIDE PORTION LOOSE	حالة المقاعد

05 Transmission Condition الجير

05.A Gear Box Visual Condition	REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	REFITTED	الفرنشل
05.C Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	PORTION CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	NOT WORKING	كشف الضباب
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	FRONT LEFT SIDE LEAK	ممتص الصدمات
08.B Other	SUSPENSION PARTS MODIFIED	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER MIRROR PORTION FADED	المرآيا
09.C AC Condition	OK	المكيف
09.D Audio	SWITCH GETTING FADED	صوتيات
09.E Dash Board	PORTION WORN OUT , MODIFIED HOLE	لوحة القيادة
09.F Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس
09.G Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carcheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carcheck.ae