CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906019
Transaction Date	27 Oct 2026, 13:00:50
Site Name	840 - Emirates Auctions
Transaction Number	61058845 (CC10021) (CC10021)



Vehicle Details

Chassis Number	JS2YC21S09*******
Specification	GCC Specification
Make	Suzuki
Model	SX 4
Model Year	2009
Color	Green
Mileage	387071 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED , BEND	وجود مؤشر لحادث في المقدمة
01.F Vehicle Color	BEIGE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS MUDDY DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NO CONTINUE STARTING ,REFITTED,PARTS GETTING RUSTY,MINOR OIL LEAK	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECK,REFITTED,PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Interior Condition		الحاله الداخليه
06.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
06.B AC Condition	NO CHECK	المكيف
06.C Dash Board	PORTION WORN OUT	لوحة القياده
06.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
06.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
06.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
06.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
06.H Engine Start Button	KEY DAMAGE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae