



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **15 Aug 2022, 16:45:52**  
 Transaction Number **47506321 (CC10008)** Queue Number **312309**



Chassis Number **KMHE241G5FA091610**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Hyundai**  
 Model **Sonata**  
 Model Year **2015**  
 Color **Blue**  
 Mileage **207715 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	NOT WORKING	المكيف
03.B Other	HAND REST LEATHER WORN OUT	اخرى
03.C Dash Board	CRACKED	لوحة القيادة
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Tail Light	REAR LEFT SIDE TAIL LIGHT LENS DAMAGED	الانارة
04.B Brake Light	NOT WORKING	نور الفرامل
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي

DEFECT	REMARKS	
05.C Rims Condition	RIMS GETTING RUSTY	حالة الجنوط
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Axel	FRONT INNER AXLE BOOT CUT	اكسلات
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	OK	الشاسيه
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	OK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.