CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945021
Transaction Date	06 Nov 2026, 16:18:10
Site Name	840 - Emirates Auctions
Transaction Number	67495685 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTDKN3DU4A*******
Specification	Imported
Make	Toyota
Model	Prius
Model Year	2010
Color	Silver
Mileage	N/A NA
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVER , MINOR DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Sign of side accident	BACK PANEL , BUMPER FRAME , QUARTER PANEL , WHEEL ARCH REPAIRED	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED , DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS LEFT SIDE FADED & RIGHT SIDE GETTING FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT & WARNING MESSAGE ON DISPLAY	ضوء تحذير
07.C Fog light	LENS GETTING FADED	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Odometer reading	ODOMETER READING NOT VISIBLE	قراءة عداد المسافات
09.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery Condition	HYBRID SYSTEM NOT WORKING , BATTERY WEAK	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae