

Queue Number	2849113	Transaction Date	08 Oct 2026, 16:49:49
Site Name	840 - Emirates Auctions	Transaction Number	31040528 (CC10013) (CC10011)



Vehicle Details

Chassis Number	SALYL2FV9K*****
Specification	Imported
Make	Range Rover
Model	Velar
Model Year	2019
Color	White
Mileage	54180 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF TRUNK,SCRATCHES,MINOR DENT & PORTION STICKER	الصبغ
01.C Doors	LEFT SIDE BOTH REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED DIRTY MUDDY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	PORTION STICKER DAMAGED	السقف
01.H Bonnet	REFITTED	غطاء المحرك
01.I Other	ELECTRIC ISSUE NOT START PROPERLY	اخرى
01.J Trunk	LUGGAGE SHADE,FUSE BOX COVER MISSING & FIBER PAINT NOT CHECK	صندوق

02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COVERED DIRTY MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه

03 Engine Condition		المحرك
03.A Engine Visual Condition	DIRTY , MUDDY , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION CRACK	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Propeller Shaft	FRONT MISSING	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
05.D Four Wheel Drive	DEFECTIVE NOT WORKING	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	EXTRA COVER	الضوء الخلفي
07.C Indicator & Hazard light	LEFT SIDE MIRROR INDICATOR LIGHT COVER REPAINTED PORTION CRACK	الاشارات
07.D Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK,CONTROLLING SWITCH PANEL PORTION MINOR CRACK	المكيف
10.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.D Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae