CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2927275
Transaction Date	31 Oct 2026, 12:49:54
Site Name	840 - Emirates Auctions
Transaction Number	64761361 (CC10013) (CC10019)



Vehicle Details

Chassis Number	KMHCT41B5H*******
Specification	GCC Specification
Make	Hyundai
Model	Accent
Model Year	2017
Color	White
Mileage	146314 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH REPAINTED ,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES.PORTION RUSTY SIGN OF HAILSTORM	الصبغ
01.C Doors	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED ,PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED PORTION MINOR DENT	الارضية
01.F Bumper	MINOR SCRATCHES	دعامية
01.G Roof	REPAINTED ,PORTION REPAIRED	السقف
01.H Bonnet	REPAINTED ,PORTION REPAIRED	غطاء المحرك
01.I Trunk	REPAINTED ,PORTION REPAIRED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION RUST PROOFED / EXTRA SCREW FIX WITH CHASSIS / CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED , ABNORMAL NOISY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Lights		**الاضاءة**
06.A Tail Light	RIGHT SIDE LIGHT NOT WORKING	الضوء الخلفي
07 Suspension System		**ممتص الصدمات**
07.A Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		**الحاله الداخليه**
08.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
08.B AC Condition	OK,ADJUSTMENT PORTION MISSING	المكيف
08.C Power Window Switch And Glass	QUARTER WINDOW COVER PORTION DAMAGED	مفتاح النافذه و الزجاج
08.D Audio	SWITCH PORTION FADED	صوتيات
08.E Dash Board	PORTION WORN OUT MELTED	لوحة القياده
09 Engine Cooling System		**نظام تبريد المحرك**
09.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae