

Queue Number

2670613

Transaction Date

22 Aug 2026, 12:53:36

Site Name

840 - Emirates Auctions

Transaction Number

26333508 (CC10009) (CC10012)



Vehicle Details

Chassis Number	JTMBD31V09*****
Specification	GCC Specification
Make	Toyota
Model	RAV 4
Model Year	2009
Color	Silver
Mileage	246792 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT SKIRT PORTION LOOSE	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	FRONT LEFT SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR THICK RUST PROOFED, MUDDY PORTION DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	RIGHT SIDE SKIRT MISSING	السقف
01.H Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.I Trunk	REPAINTED PORTION REPAIRED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL REPAIRED DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED DENT, GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED,	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS RUSTY	اخرى
09.B Mirror	ADJUSTMENT NOT WORKING	المرآيا
09.C AC Condition	OK	المكيف
09.D Dash Board	PORTION DAMAGED	لوحة القيادة
09.E Door Panel	WORN OUT	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae