

Queue Number

2873737

Transaction Date

19 Oct 2026, 17:41:50

Site Name

840 - Emirates Auctions

Transaction Number

59484889 (CC10013) (CC10019)



Vehicle Details

Chassis Number	1LN6L9PK3L*****
Specification	Imported
Make	Lincoln
Model	Continental
Model Year	2020
Color	Black
Mileage	173324 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR FULLY COVERED MUDDY SIGN OF WATER EFFECTIVE VEHICLE	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Other	VEHICLE WHILE DRIVING TURNING STEERING NOISY	اخرى
01.H Trunk	SWITCH COVER DAMAGED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى
02.C Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Belt	FRONT LEFT SIDE NOT WORKING	حزام الأمان
----------------	-----------------------------	-------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2024 & RIGHT SIDE 2019 CRACKED EXPIRED TIRE OUT OF ALIGNMENT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED INNER DAMAGED	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK / ARM DENTS SCRATCHES	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخرى
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Boot	BOOT WORN OUT	ربلة المقود
09.B Tie Rod	DENTS	رودات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
10.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Air Bag	DAMAGED	وسائد هوائية
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae