

Queue Number 2830702

Transaction Date 03 Oct 2026, 13:00:20

Site Name
840 - Emirates AuctionsTransaction Number
73445719 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WBS33BA00R*****
Specification	Imported
Make	BMW
Model	M4
Model Year	2024
Color	Unknown
Mileage	37095 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.E Bumper	FRONT SKIRT DAMAGED	دعامية
01.F Roof	CONVERTIBLE REFITTED , REPAIRED , CURTAIN PORTION FADED	السقف
01.G Trunk	FIBER PAINT NOT CHECK , REFITTED , MISALIGN	صندوق
01.H Sign of back accident	BACK PANEL QUARTER PANEL WHEEL ARCH REPAIRED	وجود مؤشر لحادث في الخلف
01.I Vehicle Color	GRAY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION REPAIRED, FRONT COVERED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY, VISUAL OK	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS GETTING RUSTY, VISUAL OK	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف
06.B Door Panel	REAR REFITTED , SCRATCHES	لوحة بطانة الباب
06.C Steering Wheel and control buttons	COVER AIRBAG REFITTED , LEATHER REPLACED	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae