CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934090
Transaction Date	03 Nov 2026, 12:50:12
Site Name	840 - Emirates Auctions
Transaction Number	41546207 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JMYSRCS1AA*******
Specification	GCC Specification
Make	Mitsubishi
Model	Lancer
Model Year	2010
Color	Silver
Mileage	504236 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END REPAIRED, REAR EXTENSION END DENT	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT.	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Indicator & Hazard light	COVER MISSING	الاشارات
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY,	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
11.B Mirror	LOOSE FADED.	المرايا
11.C Dash Board	PORTION LOOSE	لوحة القياده
11.D Sun Visor	LOOSE.	حاجب الشمس
11.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae