



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>15 Sep 2022, 10:54:56</b>
Transaction Number	<b>81603839 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>SAJAA20A3G8V97695</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Jaguar</b>
Model	<b>XJL</b>
Model Year	<b>2016</b>
Color	<b>Grey</b>
Mileage	<b>72107 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bonnet	SHOCK WEAK & REFITTED	غطاء المحرك
01.B Floor	UNDER BODY PORTION COVERED ,CHECKED VISIBLE AREA	الارضية
01.C Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
01.D Fenders	FRONT RIGHT SIDE MISALIGN	مدكار
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Power Window Switch	REAR RIGHT SIDE CARTAIN NOT WORKING	مفتاح النافذه
02.B Roof Ceiling	LOOSE	بطانه السقف
02.C Sun Visor	RIGHT SIDE LOOSE	حاجب الشمس
02.D Dash Board	CENTER CONSOLE BOX COVER DAMAGE	لوحة القيادة
02.E Other	STARTING SWITCH BUTTON BROKEN	اخرى
02.F Door Panel	INNER COVER REXIN LOOSE .	لوحة بطانه الباب
02.G AC Condition	OK	المكيف
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي

DEFECT	REMARKS	
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	REFITTED, OIL LEAK	حالة المحرك النظرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	REFITTED, OIL LEAK	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Suspension Subframe	REFITTED	
06.B Arms	LOWER ARM BUSHES CUT	ازرع
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	FRONT RIGHT SIDE CHASSIS JOINT AREA DENT .	الشاسيه
<b>08 Exhaust System</b>		<b>نظام العادم</b>
08.A Other	SILENCER MUFFLER DENT	اخرى
08.B Modification	EXHAUST LEAKING	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Transfer Certificate :	66870512
Chassis No :	SAJAA20A3G8V97695
Vehicle Make :	JAGUAR
Vehicle Model :	XJL
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	72112 Kms. <span style="color: red;">x</span>
Origin : United Kingd...	Model Year : 2016
Gear Type : Automatic	Engine Size : 3000 CC
Engine No : 16011312243...	Horse : 243
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2400 Kgs.	Empty : 1874 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17654256		
Inspection Date :	18-09-2022		
Certificate Print Date :	18-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	1 min 30 sec		
Appointment Ref Number :	--		
Start Time :	13:56	End Time :	13:57
Lane :	03	Token No. :	193
Attempt :	2	Prints No. :	3

## Carbon footprint



Take action to protect Dubai environment

## Estimated Vehicle Consumption (Rate last 12 Months)

34613 KM	3562 L	11862 AED	8.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks: engine minor oil leak/



### Odometer Record

Replace Events Date

18/09/2022

## Payment Details

Inspection Performed by 6831	Payment Method Cash	Transaction Number 17654256	Service Fees AED 70 Collected on 18/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

