



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Oct 2021, 18:24:39
Transaction Number	20876192 (CC10006)	Queue Number	312309



Chassis Number	WP1ZZZ92ZBLA55075
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne S
Model Year	2011
Color	Brown
Mileage	95393 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
02.B Doors	PORTION REPAIRED & REPAINTED	أبواب
02.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
02.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
02.E Floor	UNDER FLOOR PORTION COVER & SLYDING NOT WORKING PROPERLY	الارضية
02.F Bumper	REPAINTED	دعامية
02.G Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
02.H Trunk	REPAINTED & SHEILD MISSING	صندوق
02.I Roof	SLYDING ROOF INNER SHEILD NOT WORKING	السقف
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis	VISABLE AREA OK	الشاسيه

DEFECT	REMARKS	
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Engine Condition	OIL LEAK	حالة المحرك
<b>05 Exhaust System</b>		<b>نظام العادم</b>
05.A Other	WELDED	اخرى
05.B Modification	MODIFIED	تعديلات
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	OK	الاضاءة الرئيسية
<b>08 Interior Condition</b>		<b>الحالة الداخلية</b>
08.A Power Window Switch	REAR RIGHT SIDE DAMAGED & REAR BOTH SIDE GLASS WINDOW NOT WORKING	مفتاح النافذه
08.B Roof Ceiling	REAR REFITTED & LOSE	بطانه السقف
08.C AC Condition	A/C GRAIL DAMAGED & NOT WORKING PROPERLY	المكيف
08.D Dash Board	COVER LOSE	لوحة القيادة
08.E Mirror	CENTER MIRROR FADED	المرايا
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
<b>10 Transmission Condition</b>		<b>الجير</b>
10.A Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.