



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 May 2022, 12:25:38
Transaction Number	85198824 (CC10008)	Queue Number	312309



Chassis Number	JN8AY25Y7B9009126
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2011
Color	White
Mileage	210270 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Dash Board	CRACKED	لوحة القيادة
01.B Power Window Switch	FRONT POWER WINDOW SWITCH BUTTON MISSING	مفتاح النافذه
01.C Mirror	FOLDING SIDE MIRROR NOT WORKING	المرايا
01.D AC Condition	LEFT SIDE AC NOT COOLING & REAR AC SWITCH NOT WORKING	المكيف
01.E Door Panel	REAR DOOR PANEL PORTION DAMAGED	لوحة بطانة الباب
02 Body		جسم المركبة
02.A Trunk	NOT OPENING & OPENING BUTTON DAMAGED	صندوق
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Other	FRONT LEFT SIDE FENDER FRAME .RADIATOR SUPPORT REPAIRED	اخرى
02.D Bonnet	SHOCK WEAK	غطاء المحرك
02.E Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT ,SCRATCHES	الصبغ
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED & WORN OUT	الاطار الخلفي
03.B Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط

DEFECT	REMARKS	
03.C Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	OK	حالة الجير النظري
05 Chassis Condition		الشاصي
05.A Chassis	OK & CHASSIS FRAME GETTING MINOR RUSTY	الشاسيه
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Engine Condition		المحرك
07.A Visual Engine Condition	SHAKING,MISFIRING & RPM HIGH	حالة المحرك النظري
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	SHOCK ABSORBER MINOR OIL LEAK	ممتص الصدمات
08.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
09 Seats Condition		المقاعد
09.A Seat Condition	DRIVER SEAT LOOSE	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.