CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2971037
Transaction Date	11 Nov 2026, 13:47:29
Site Name	840 - Emirates Auctions
Transaction Number	83910359 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBAKB4107A*******
Specification	GCC Specification
Make	BMW
Model	740 I
Model Year	2010
Color	Gold
Mileage	105809 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE PORTION REPAINTED & RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Windshield	REAR CURTAIN NOT WORKING	زجاج
01.G Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAMERADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY, SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT BACK COVER PORTION LOOSE	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL WET REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH WORN OUT MELTED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CUT	ازرع
08.B Other	SUSPENSION REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INNER PARTS GETTING RUSTY	اخري
09.B Roof Ceiling	PORTION LOOSE	بطانه السقف
09.C Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae