CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2919278
Transaction Date	28 Oct 2026, 16:42:51
Site Name	840 - Emirates Auctions
Transaction Number	39002557 (CC10009) (CC10012)



Vehicle Details

Chassis Number	SALWZ2SE5K*******
Specification	Imported
Make	Range Rover
Model	Sport
Model Year	2019
Color	Unknown
Mileage	54630 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS COMPLETELY COVERED	الارضية
01.D Windshield	FRONT SPOT CRACK	زجاج
01.E Bonnet	FIBER PAINT NOT CHECK , REFITTED , PORTION CRACK	غطاء المحرك
01.F Trunk	FIBER PAINT NOT CHECK , MISALIGN	صندوق
01.G Vehicle Color	WHITE BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY,OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY	اخري
02.C Chassis Number	LAMINITED CHECKED ON STICKER ONLY	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY, DELAY STARTING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , FRONT RIGHT SIDE HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNIONG LIGHT IN DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Hydraulic System	NOT WORKING	النظام الهيدروليكي
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY , (SING OF FLOODED)ELECTRIC FAULT	اخري
09.B AC Condition	OK	المكيف
09.C Roof Ceiling	LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae