CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877800
Transaction Date	16 Oct 2026, 16:15:13
Site Name	840 - Emirates Auctions
Transaction Number	27492722 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JNKCV64E09*******
Specification	GCC Specification
Make	Infiniti
Model	G 37
Model Year	2009
Color	Silver
Mileage	158799 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE REPAITED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES , PORTION FADED , GETTING RUSTY	الصبغ
01.C Doors	LEFT SIDE OUTER A PILLAR PANEL DAMAGE	أبواب
01.D Floor	PORTION DENT	الارضية
01.E Bumper	MISALIGN , SCRATCHES	دعامية
01.F Roof	REPAINTED , PORTION FADED	السقف
01.G Bonnet	REPAINTED	غطاء المحرك
01.H Sign of side accident	REAR LEFT SIDE FENDER BADLY DAMAGE	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY , OILLY MUDDY	الشاسيه
03 Engine Condition		المحرك
03.A Mount	LOWER MOUNT BUSHES CRACK	كرسي
03.B Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK MUDDY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS GETTING RUSTY , MINOR JERKING	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	RIGHT SIDE 2022 CRACK & LEFT SIDE 2023	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2025 & RIGHT SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
10 Steering Condition		المقود
10.A Steering Box	SIGN OF OIL WET	جهاز المقود
10.B Tie Rod End	BOOT CRACK	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY	اخري
11.B AC Condition	OK	المكيف
11.C Power Window Switch And Glass	MAIN SWICTH LEFT SIDE & FRONT RIGTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.D Audio	LCD SCREEM FADED	صوتيات
11.E Dash Board	PORTION WORN OUT	لوحة القياده
11.F Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.G Door Panel	WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	PORTION WORN OUT , RIGHT SIDE CONTROL STICK DAMAGE	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae