CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2891524
Transaction Date	22 Oct 2026, 17:01:32
Site Name	840 - Emirates Auctions
Transaction Number	85121465 (CC10010) (CC10010)



Vehicle Details

Chassis Number	RKLBB9HE8H*******
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2017
Color	White
Mileage	360610 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAIRED REPAINTED , REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY., RUNNING BOARD DENT .	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED . REFITTED.	غطاء المحرك
01.H Trunk	NOT CLOSSING. REPAINTED REPAIRED REFITTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	QUARTER PANEL WHEEL ARCH ,PILLAR OUTER PANEL REPAIRED,	وجود مؤشر لحادث في الجانب
01.K Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASIS DENT MUDDY OILY , CHECKED ONLY VISIBE AREA.	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION DAMAGE.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 PUNCTURE	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 PUNCTURE	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED,	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07.C Fog light	LOOSE	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX DAMAGED . INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
09.B Mirror	LOOSE INNER SIDE COVER MISSING	المرايا
09.C AC Condition	NOT COOLING ..	المكيف
09.D Dash Board	MELTED CRACKED PORTION CUT .	لوحة القياده
09.E Roof Ceiling	PORTION LOOSE	بطانه السقف
09.F Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT PORTION DAMAGED	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae