

Queue Number 2894874

Transaction Date 22 Oct 2026, 17:01:18

Site Name  
840 - Emirates AuctionsTransaction Number  
58477545 (CC10013) (CC10011)

## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | WDGDA7EB1D*****   |
| Specification     | GCC Specification |
| Make              | Mercedes          |
| Model             | ML 63             |
| Model Year        | 2013              |
| Color             | White             |
| Mileage           | 83334 Km          |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 8                 |

| Condition | Remarks | الحالة |
|-----------|---------|--------|
|-----------|---------|--------|

## 01 Body جسم المركبة

|              |                                                                                 |             |
|--------------|---------------------------------------------------------------------------------|-------------|
| 01.A Fenders | FRONT BOTH SIDE REPAINTED PORTION REPAIRED REFITTED,RIGHT SIDE SKIRT MISSING    | مدكار       |
| 01.B Paint   | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES(BODY KIT MODIFIED) | الصبغ       |
| 01.C Rusty   | UNDER FLOOR SUSPENSION PARTS GETTING RUSTY                                      | صدأ         |
| 01.D Floor   | UNDER FLOOR PORTION COVERED DIRTY                                               | الارضية     |
| 01.E Bumper  | MISALIGN PORTION DAMAGED,LOGO MISSING                                           | دعامية      |
| 01.F Bonnet  | REPAINTED PORTION REPAIRED REFITTED,STAY SHOCK NOT WORKING                      | غطاء المحرك |
| 01.G Trunk   | LOGO MISSING                                                                    | صندوق       |

## 02 Chassis Condition الشاسيه

|              |                                                      |         |
|--------------|------------------------------------------------------|---------|
| 02.A Chassis | CHASSIS PORTION COVERED CHECK VISIBLE AREA ONLY / OK | الشاسيه |
|--------------|------------------------------------------------------|---------|

## 03 Engine Condition المحرك

|                              |                                                                |                       |
|------------------------------|----------------------------------------------------------------|-----------------------|
| 03.A Other                   | UPPER COVER PART MISSING                                       | اخرى                  |
| 03.B Engine Visual Condition | OPEN REFITTED , PARTS GETTING RUSTY , OIL WET , ABNORMAL NOISY | الحالة النظرية للمحرك |

## 04 Seats Condition المقاعد

|                     |                                        |              |
|---------------------|----------------------------------------|--------------|
| 04.A Seat Condition | FRONT RIGHT SIDE BRACKET COVER MISSING | حالة المقاعد |
|---------------------|----------------------------------------|--------------|

## 05 Exhaust System نظام العادم

|                   |                         |         |
|-------------------|-------------------------|---------|
| 05.A Modification | EXHAUST SYSTEM MODIFIED | تعديلات |
|-------------------|-------------------------|---------|

| Condition                          | Remarks                                                                                     | الحالة                 |
|------------------------------------|---------------------------------------------------------------------------------------------|------------------------|
| <b>06 Transmission Condition</b>   |                                                                                             | <b>الجير</b>           |
| 06.A Gear Box Visual Condition     | REFITTED , PARTS GETTING RUSTY                                                              | الحالة النظرية للجير   |
| 06.B Road Test                     | NOT CHECKED                                                                                 | فحص علي الطريق         |
| <b>07 Tires and Rims Condition</b> |                                                                                             | <b>الاطارات</b>        |
| 07.A Front Tyre                    | BOTH SIDE 2025 GETTING WORN OUT                                                             | الاطار الامامي         |
| 07.B Rear Tyre                     | BOTH SIDE 2025                                                                              | الاطار الخلفي          |
| 07.C Rims Condition                | MINOR DENT SCRATCHES / EXTRA SPACER                                                         | حالة الجنوط            |
| <b>08 Lights</b>                   |                                                                                             | <b>الاضاءة</b>         |
| 08.A Tail Light                    | PORTION CRACK                                                                               | الضوء الخلفي           |
| 08.B Warning Light                 | WARNING LIGHT ON DISPLAY                                                                    | ضوء تحذير              |
| <b>09 Interior Condition</b>       |                                                                                             | <b>الحالة الداخلية</b> |
| 09.A Mirror                        | CENTER VIEW MIRROR BACK COVER PORTION LOOSE,RIGHT SIDE DAMAGED,INTERIOR PARTS GETTING RUSTY | المرآيا                |
| 09.B AC Condition                  | OK                                                                                          | المكيف                 |
| 09.C Power Window Switch And Glass | SWITCH PORTION GETTING FADED                                                                | مفتاح النافذه و الزجاج |
| 09.D Audio                         | SWITCH GETTING FADED                                                                        | صوتيات                 |
| 09.E Dash Board                    | LEATHER PORTION LOOSE WORN OUT                                                              | لوحة القيادة           |
| 09.F Odometer reading              | CLUSTER PANEL LOOSE                                                                         | قراءة عداد المسافات    |
| 09.G Engine Start Button           | NOT WORKING PROPERLY,SMART KEY MISSING                                                      | زر تشغيل المحرك        |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](http://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](http://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

للشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)