





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26032468	Plate Category	: PRIVATE
Transaction Date	: 03 MAY 2021 09:26:27	Plate Number	: 552941 EA
Queue Number	: 329371	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y86X552941	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
02.06 - Steering Wheel Alignment		میزانية عجلة القيادة
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.17 - Gear Box Mounting		كراسي ناقل الحركة
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصبغ
05.03 - Doors		الابواب
05.08 - Chassis (Frame)		لتشاصية
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرآيا الجانبية
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
06.21 - Battery Condition		حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26032468	Plate Category	: PRIVATE
Transaction Date	: 03 MAY 2021 09:26:27	Plate Number	: 552941 EA
Queue Number	: 329371	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y86X552941	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.14 - Sign Of Front Accident	RIGHT FENDER FRAME/ BULKHEAD/ RADIATOR SUPPORT REPAIRED/ FENDERS & HOOD REFITTED	أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling	LOW COOLING	عطل في المكيف
09.25 - Body Repainted		أثر صنيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate



X FAILED

Plate Details :	--
Chassis No :	JN8FY15Y86X552941
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	537054 Kms.
Origin :	Japan
Model Year :	2006
Gear Type :	--
Engine Size :	3500 CC
Engine No :	TB48037129
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	3000 Kgs.
Empty Weight :	2000 Kgs.

Certificate Number :	5-TAS-2021-14150004
Inspection Date :	06-05-2021
Certificate Print Date :	06-05-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	11 min 18 sec
Appointment Ref Number :	--
Start Time :	12:35
End Time :	12:47
Lane :	01
Token No. :	10
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	7 %	4 %	0.4 %
Vehicle on Petrol HC Reading			
44 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tire	Date of manufactured tampered or expired	Major
CHANGE ALL 4 TIRES DOT 2005/ 2014/ 2016 OLD EXPIRED		
Warning triangle	Missing	Major
Rim	Missing bolts and nuts (Major)	Major
FIX ALL MISSING LUG NUTS		

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	4800	

Inspection Remarks:

REAR LEFT CHASSIS INNER BULGED/ RIGHT FENDER FRAME/ BULKHEAD/ RADIATOR SUPPORT REPAIRED/ REAR RIGHT DOOR PILLAR REPAIRED/ DENT/ BODY MINOR SCRATCHES/ ROMANO SEALS MINOR LEAK

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
74791	VTP Credit Account	14150004	AED 170 Collected on 06/05/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Raul Canceran Galang

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995
This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995



