

TEST CERTIFICATE

Site Number
Transaction Number

05.A Ball Joint

05.B Arms

840-Emirates Auctions 25190966 (CC10006) Transaction Date

31 Jul 2022, 16:08:29

Queue Number

312309

Chassis Number

er

SALGA2DF7FA203128

Engine Number

Vehicle Class

Car

Manufacturer

Range Rover

Model

--

Model Year

2015

Color

White

Mileage

110435 Km

Fuel Type

Petrol

No. Of Cylinders

8

Specification

GCC Specification

مفصل کروی

ازرع

REMARKS DEFECT 01 Interior Condition الحاله الداخليه 01.A AC Condition OK المكيف **02 Lights** الاضاءة WARNING LIGHT ON DISPLAY 02.A Warning Light ضوء تحذير **03 Tires and Rims Condition** الاطارات **BOTH SIDE 2020** 03.A Front Tyre الاطار الامامى 03.B Rear Tyre **BOTH SIDE 2020** الاطار الخلفى 03.C Rims Condition RIMS HAVE MINOR DENT SCRATCHES حالة الجنوط **04 Transmission Condition** الجير 04.A Road Test **NOT CHECK** فحص علي الطريق 04.B Visual Gear Box MINOR OIL LEAK حالة الجير النظرى Condition 04.C Gear Box Mount MOUNT RUBBER CRACKED كرسي الجير **05 Suspension System** ممتص الصدمات

BOOT CRACKED

FRONT LOWER ARM BUSH CRACKED

DEFECT	REMARKS	
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
O8 Body		جسم المركبة
08.A Paint	BODY MINOR DENT ,SCRATCHES (VEHICLE MODEL HSE ON THE BODY)	الصبغ
08.B Floor	UNDER FLOOR CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACKED	مؤخرة الرودات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.