





Test Certificate

| | | | |
|---------------------|--------------------------|--------------------|----------------|
| Site Number | : 840-TASJEEL EM AUCTION | Plate Code | : 0 |
| Transaction Number | : 19237212 | Plate Category | : PRIVATE |
| Transaction Date | : 20 FEB 2020 11:28:16 | Plate Number | : 1744 EA |
| Queue Number | : 147293 | Import Doc. Ref. | : |
| Chassis Number | : JTDKW923785111744 | Manufacturer/Model | : TOYOTA/YARIS |
| Engine Number | : | Model Year | : 2008 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : SILVER |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--|------------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Failed | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.11 - Shock Absorbers | REAR BOTH SHOCK ABSORBERS LEAK | مخمد الصدمات |
| 03 Brake System | | نظام الفرامل |
| 03.01 - Brake Efficiency Front Wheels Left And Right Hands | BRAKE ROTORS RUSTY | قوة فرامل المحور الامامي |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | AL TYRES DOT 2017 & 2018 | الاطارات الامامية |
| 04.08 - Spare Tires | MISSING | الاطار الاحتياطي |
| 05 Body | | الهيكل |
| 05.02 - Paint | BODY SCRATCHES & DENTS | الصبغ |
| 05.07 - Floor | FLOOR REINFORCEMENTS SCRATCHES & DENTS | الارضية |
| 06 General Items | | الاشياء العامة |
| 06.12 - Seats Condition And Seats Fixing | INTERIOR PARTLY WORN OUT | المقاعد وحالتها وتثبيتها |
| 06.14 - Transmission Condition | OK | حالة ناقل الحركة |
| 06.16 - Engine Condition, Smoke | ENGINE MISFIRING/ VIBRATION/ LOW POWER | حالة المحرك - الدخان |
| 07 Remarks | | ملاحظات |
| 07.04 - Others | 396942 KMS | ملاحظات اخرى |
| 09 Auction | | الفحص الكامل |
| 09.02 - Need Wheel Alignment | | يحتاج الى ميزانية العجلات |
| 09.06 - Chassis Ok | | النشاصي جيد |
| 09.14 - Sign Of Front Accident | | أثر حادث في مقدمة المركبة |
| 09.16 - Sign Of Side Accident | | أثر حادث في جوانب المركبة |
| 09.18 - A/C Not Cooling | | عطل في المكيف |



Test Certificate

| | | | |
|---------------------|--------------------------|--------------------|----------------|
| Site Number | : 840-TASJEEL EM AUCTION | Plate Code | : 0 |
| Transaction Number | : 19237212 | Plate Category | : PRIVATE |
| Transaction Date | : 20 FEB 2020 11:28:16 | Plate Number | : 1744 EA |
| Queue Number | : 147293 | Import Doc. Ref. | : |
| Chassis Number | : JTDKW923785111744 | Manufacturer/Model | : TOYOTA/YARIS |
| Engine Number | : | Model Year | : 2008 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : SILVER |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| | |
|--|---------------------|
| 09.25 - Body Repainted | أثر صدىغ في المركبة |
| The Test Certificate Shows the test Result at the time of inspection only. | |