



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 18:09:31
Transaction Number	71251036 (CC10006)	Queue Number	312309



Chassis Number	JN8AY25Y8A9004418
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2010
Color	White
Mileage	84186 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Dash Board	PORTION CRACKED	لوحة القيادة
01.C Sun Visor	LEFT SIDE LOOSE	حاجب الشمس
01.D Power Window Switch	MAIN SWITCH FRONT BUTTON DAMAGED	مفتاح النافذه
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019 , WORN OUT	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	MINOR OIL LEAK & REFITTED, SHAKING	حالة الجير النظري
03.C Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
04 Body		جسم المركبة
04.A Paint	BODY PORTION REPAIRED, REPAINTED, MINOR DENT, SCRATCHES	الصبغ
04.B Fenders	FRONT BOTH SIDE REAR RIGHT SIDE PORTION REPAIRED	مدكار

DEFECT	REMARKS	
	REPAINTED	
04.C Doors	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED & REAR RIGHT SIDE REPAINTED	أبواب
04.D Trunk	TAIL GATE PORTION REPAIRED REPAINTED , AUTO BUTTON DAMAGED	صندوق
04.E Bonnet	SHOCK WEAK, PORTION REPAIRED REPAINTED	غطاء المحرك
04.F Other	REAR RIGHT SIDE QUARTER PANEL REPAIRED	اخرى
05 Engine Condition		المحرك
05.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
05.B Smoke	BLACK SMOKE	دخان
05.C Mount	MOUNT BUSH CRACKED	كرسي
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
07 Chassis Condition		الشاسي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.