

Queue Number 1848190

Transaction Date 09 Oct 2025, 16:33:54

Site Number
840 - Emirates AuctionsTransaction Number
77759800 (CC10018) (CC10012)

Vehicle Details

Chassis Number	SCA689X00K*****
Specification	Imported
Make	Rolls Royce
Model	Cullinan
Model Year	2019
Color	--
Mileage	88520 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY THICK DUST , PAINT CANNOT CHECK PROPERLY & STRIP PORTION RUSTY	الصبغ
01.B Floor	UNDER FLOOR FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.C Windshield	TOTALLY THICK DUST, VISIBILITY NOT CLEAR	زجاج
01.D Bonnet	OPENING HANDLE DAMAGED	غطاء المحرك
01.E Trunk	REFITTED & MISALIGN	صندوق
01.F Door Handle & Lock	REAR BOTH SIDE BUTTON LOCK NOT WORKING	مقابض الأبواب والأقفال
01.G Vehicle Color	BLUE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN LAMINATED	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK, PARTS REFITTED	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	REAR BOTH SIDE ADJUSTMENT NOT WORKING & FRONT BOTH SIDE BACK BUTTON ADJUSTMENT NOT WORKING	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK, PARTS REFITTED	الحالة النظرية للجير
05.B Propeller Shaft	FLANGE RUBBER DAMAGED	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022, DRY CRACKED, WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022, DRY CRACKED, WORN OUT	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES & REAR RIGHT SIDE HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPALY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSH CRACKED	ازرع
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK	المكيف
09.B Power Window Switch And Glass	WINDOW CENTER LOCK BUTTON NOT WORKING	مفتاح النافذه و الزجاج
09.C Audio	REAR BOTH SIDE BACK LCD FOLDING NOT WORKING	صوتيات
09.D Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae