CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2916437
Transaction Date	28 Oct 2026, 14:59:08
Site Name	840 - Emirates Auctions
Transaction Number	94625972 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WBSEK910X8*******
Specification	GCC Specification
Make	BMW
Model	M6
Model Year	2008
Color	Black
Mileage	117542 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	10

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR PORTION DENT, FRONT CHASSIS COVERED	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Door Handle &Lock	BOTH SIDE AUTO NOT WORKING	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OPEN REFITTED OILLEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT RIGHT SIDE LEATHER PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OPEN REFITTED , MINOR OIL LEAK	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LENS GETTING FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR REFITTED	اخري
09.B Mirror	BOTH SIDE FOLDING NOT WORKING , LEFT SIDE MIRROR FADED	المرايا
09.C AC Condition	OK	المكيف
09.D Dash Board	LEATHER REPLACED , PORTION LOOSE , SPICKER PANEL DAMAGED	لوحة القياده
09.E Odometer reading	DISPLAY FADED	قراءة عداد المسافات
09.F Door Panel	LEATHER MINOR LOOSE , RIGHT SIDE HANDLE INNER LOOSE	لوحة بطانة الباب
09.G Sunroof	LOCK BUTTON MISSING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae