

Queue Number

2840685

Transaction Date

06 Oct 2026, 13:44:03

Site Name

840 - Emirates Auctions

Transaction Number

51503611 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WVWZZZ1JZ2*****
Specification	Imported
Make	Volkswagen
Model	Golf
Model Year	2002
Color	Red
Mileage	146409 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.E Roof	REPAINTED PORTION REPAIRED	السقف
01.F Bonnet	REFITTED , REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OPEN REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET,DELAY START ABNORMAL NOISY ,SHAKING.	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , EXTRA COVER	حالة المقاعد
---------------------	-----------------------------	--------------

05 Exhaust System

نظام العادم

05.A Modification	CUT REWELDED	تعديلات
-------------------	--------------	---------

Condition	Remarks	الحالة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OPEN REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET,JERKING.	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	LEFT SIDE 2021 RIGHT SIDE 2001 EXPIRED CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES , FRONT BOTH SIDE WHEEL HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Indicator & Hazard light	BOTH SIDE INDICATOR LIGHT COVER MISSING	الاشارات
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	WEAK,	ممتص الصدمات
10.B Arms	BUSHES CUT	ازرع
11 Steering Condition		المقود
11.A Tie Rod	BOOT CUT	رودات
11.B Axle	BOOT CUT	اكسلات
12 Interior Condition		الحاله الداخليه
12.A Other	CENTER CONSOLE BOX DAMAGE	اخرى
12.B Mirror	CENTER MIRROR GETTING FADED	المرايا
12.C AC Condition	NOT COOLING.	المكيف
12.D Floor Matting	DIRTY	فرش الأرضيه
12.E Dash Board	PORTION WORN OUT	لوحة القيادة
12.F Roof Ceiling	PANEL CASE CRACK	بطانه السقف
12.G Air Bag	FRONT RIGHT SIDE COVER LOOSE	وسائد هوائية
12.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.I Gear Shifting Lever	KNOB WORN OUT , SHIFTER PANEL SLIDE COVER MISSING	ذراع نقل السرعات
12.J Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
13 Engine Cooling System		نظام تبريد المحرك
13.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae