CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906013
Transaction Date	28 Oct 2026, 15:00:50
Site Name	840 - Emirates Auctions
Transaction Number	84592079 (CC10010) (CC10010)



Vehicle Details

Chassis Number	SALLMAM346*******
Specification	GCC Specification
Make	Range Rover
Model	Vogue
Model Year	2006
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Windshield	SIDE COVER CRACKED.	زجاج
01.F Bonnet	SKIRT MISSING	غطاء المحرك
01.G Fuel Tank	LID COVER MISSING	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA PORTION DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED DAMAGED CRACKED.	الاطار الامامي
06.B Rear Tyre	EXPIRED DAMAGED CRACKED.	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CUT .	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	BOTH SIDE MIRROR MISSING.	المرايا
11.C AC Condition	NOT CHECKED ,GRILL LOOSE.	المكيف
11.D FLoor Matting	CENTER CONSOLE ASSEMBLY DAMAGED.	فرش الأرضيه
11.E Dash Board	DAMAGED PORTION LOOSE LEATHER REPLACED. GLOVE BOX NOT OPEN	لوحة القياده
11.F Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.G Sun Visor	LOOSE.	حاجب الشمس
11.H Odometer reading	NOT CHECKED.	قراءة عداد المسافات
11.I Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.K Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**