

Queue Number 2920037

Transaction Date 29 Oct 2026, 13:22:57

Site Name
840 - Emirates AuctionsTransaction Number
63592818 (CC10009) (CC10012)

Vehicle Details

Chassis Number	1C4RJKAG3R*****
Specification	Imported
Make	Jeep
Model	Grand Cherokee
Model Year	2024
Color	Unknown
Mileage	40509 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED , RIGHT SIDE REPAINTED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTIN RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED , MISALIGN	غطاء المحرك
01.H Pillars	RIGHT SIDE A / PILLAR PORTION DENT	القوائم
01.I Sign of side accident	FRONT RIGTHT SIDE WHEEL ARCH BARCKET DENT	وجود مؤشر لحادث في الجانب
01.J Vehicle Color	GREY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH RIGHT SIDE CHASSIS & REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	------------------------	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Brake Condition		الفرامل
06.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
07 Suspension System		ممتص الصدمات
07.A Other	SUSPENSION REFITTED	اخرى
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Other	WARNING LIGHT AND HAVE PLY	اخرى
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY , (SING OF FLOODED) , INTERIOR REFITTED	اخرى
09.B AC Condition	OK	المكيف
09.C Floor Matting	FRONT RIGHT SIDE MISSING	فرش الأرضيه
09.D Dash Board	PANEL MISALIGN	لوحة القيادة

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae