

Queue Number

2870281

Transaction Date

19 Oct 2026, 17:41:42

Site Name

840 - Emirates Auctions

Transaction Number

35762535 (CC10013) (CC10011)



Vehicle Details

Chassis Number

WBSGZ010XC*****

Specification

GCC Specification

Make

BMW

Model

X6

Model Year

2012

Color

Red

Mileage

109459 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT OUTER STRIP MISSING / FRONT FIBER PAINT NOT CHECK REFITTED,REAR LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,PORTION GETTING FADED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT BOTH & REAR RIGHT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED MINOR DENT	الارضية
01.F Bumper	MISALIGN , SCRATCHES	دعامية
01.G Windshield	FRONT CRACKED	زجاج
01.H Bonnet	LEFT SIDE GRILL MISSING , REFITTED	غطاء المحرك
01.I Trunk	NOT CLOSE / PORTION REPAINTED REPAIRED	صندوق
01.J Fuel Tank	DENT	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER COVER FOR RECHECK	اخرى
02.C Chassis Number	DOOR POST STICKER WORN OUT DAMAGED	رقم القاعدة

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Other	UPPER COVER MISSING , OIL CAP DAMAGED	اخرى
03.B Engine Visual Condition	NOT START ALL SYSTEM NOT CHECK REFITTED , PARTS MISSING , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2025 BOTH SIDE	الاطار الامامي
06.B Rear Tyre	2025 BOTH SIDE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طناير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Boot	BOOT WORN OUT	ربلة المقود
10.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY , DIRTY / TEA CUP HOLDER SLIDING COVER DAMAGED	اخرى
11.B AC Condition	NOT CHECKED	المكيف
11.C Roof Light	COVER MISSING	أنارة السقف
11.D Dash Board	GETTING FADED PORTION CRACK WORN OUT	لوحة القيادة
11.E Roof Ceiling	LOOSE	بطانه السقف
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae