



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>15 Sep 2021, 12:32:20</b> |
| Transaction Number | <b>85945805 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                |                          |
|----------------|--------------------------|
| Chassis Number | <b>MMBJNKL40GH057974</b> |
| Engine Number  |                          |
| Vehicle Class  | <b>Car</b>               |
| Manufacturer   | <b>Mitsubishi</b>        |
| Model          |                          |
| Model Year     | <b>2016</b>              |
| Color          | <b>--</b>                |
| Mileage        | <b>370593</b>            |

| DEFECT                             | REMARKS  |                    |
|------------------------------------|--|--------------------|
| <b>01 Body</b>                     |  | <b>جسم المركبة</b> |
| 01.A Paint                         | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ              |
| 01.B Rusty                         | UNDER BODY PARTS, CHASSIS FRAME RUSTY                  | صدأ                |
| 01.C Floor                         | UNDER FLOOR MUDY                                       | الارضية            |
| 01.D Roof                          | PORTION REPAIRED & REPAINTED                           | السقف              |
| 01.E Bonnet                        | REPAIRED & REPAINTED                                   | غطاء المحرك        |
| 01.F Windshield                    | REPLACED   | زجاج               |
| <b>02 Chassis Condition</b>        |  | <b>الشاسي</b>      |
| 02.A Chassis                       | OK   | الشاسيه            |
| <b>03 Engine Condition</b>         |  | <b>المحرك</b>      |
| 03.A Other                         | OK   | اخرى               |
| <b>04 Seats Condition</b>          |  | <b>المقاعد</b>     |
| 04.A Other                         | OK   | اخرى               |
| <b>05 Transmission Condition</b>   |  | <b>الجير</b>       |
| 05.A Gear Box                      | OK   | الجير              |
| <b>06 Tires and Rims Condition</b> |  | <b>الاطارات</b>    |
| 06.A Front Tyre                    | BOTH SIDE 2020   | الاطار الامامي     |
| 06.B Rear Tyre                     | BOTH SIDE 2020   | الاطار الخلفي      |

| DEFECT                       | REMARKS                                       |                         |
|------------------------------|---|-------------------------|
| <b>07 Wipers and Arms</b>    |   | <b>المساحات</b>         |
| 07.A Other                   | OK  | اخرى                    |
| <b>08 Lights</b>             |   | <b>الاضاءة</b>          |
| 08.A Head Light              | LENS SLIGHTLY FADED                           | الاضاءة الرئيسية        |
| 08.B Other                   | OK  | اخرى                    |
| <b>09 Brake Condition</b>    |   | <b>الفرامل</b>          |
| 09.A Caliber Brake           | GETTING RUSTY                                 | جهاز الفرامل            |
| <b>10 Suspension System</b>  |   | <b>ممتص الصدمات</b>     |
| 10.A Leaf Spring             | BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY |                         |
| <b>11 Interior Condition</b> |   | <b>الاجزاء الداخلية</b> |
| 11.A Other                   | OK  | اخرى                    |
| 11.B Mirror                  | OK  | المرايا                 |
| 11.C AC Condition            | OK  | المكيف                  |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.