CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3007895
Transaction Date	18 Nov 2026, 16:41:11
Site Name	840 - Emirates Auctions
Transaction Number	45332464 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JN8AY25Y2C*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2012
Color	White
Mileage	133555 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH PORTION REPAINTED & FRONT RIGHT SIDE REPAINTED,PORTION REPAIRED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Doors	FRONT BOTH SIDE & REAR LEFT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR FULLY MUDDY, RIGHT SIDE FOOTREST PORTION DAMAGED LEFT SIDE LOOSE	الارضية
01.F Roof	REPAINTED,PORTION REPAIRED	السقف
01.G Bonnet	REPAINTED,REFITTED ,SHOCK NOT WORKING	غطاء المحرك
01.H Other	BODY SHAPE CHANGED	اخري
01.I Trunk	REPAINTED,PORTION REPAIRED ,NOT OPEN ,SWITCH DAMAGED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY /OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	EXTRA COVER PORTION CUT & REAR CENTER HEADREST MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES ,HUB COVER MISSING	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	FRONT LEAK	ممتص الصدمات
07.B Arms	LOWER ARMB BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Oil	MINOR OIL EAK	زيت المقود
08.B Steering Boot	BOOT CUT	ربلة المقود
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY WATER FLOODED & INETRIOR MODIFIED	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	LEATHER PORTION LOOSE	لوحة القياده
09.D Steering Wheel and control buttons	PORTION DAMAGED	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	GEAR LOCK COVER MISSING & KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae