

Queue Number 2848762

Transaction Date 10 Oct 2026, 09:49:14

Site Name
840 - Emirates AuctionsTransaction Number
31033035 (CC10010) (CC10010)

Vehicle Details

Chassis Number LSJA36E3XN*****
 Specification GCC Specification
 Make MG
 Model MG 5
 Model Year 2022
 Color Silver
 Mileage N/A Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE PORTION REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.E Bumper	MINOR SCRATCHES.	دعامية
01.F Trunk	NOT OPEN ,REPAINTED PORTION REPAIRED.	صندوق
01.G Sign of back accident	BUMPER REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الامامي
-----------------	---	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06 Lights		
06.A Head Light	LENS GETTING FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		
07.A Disc&Drum	PARTS RUSTY.	دسك و طناوير الفرامل
08 Suspension System		
08.A Arms	BUSHES DRY CRACKED.	ازرع
09 Interior Condition		
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخرى
09.B AC Condition	NOT CHECKED.	المكيف
09.C Odometer reading	NOT CHECKED .	قراءة عداد المسافات
09.D Steering Wheel and control buttons	GETTING WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae