



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Jan 2023, 13:54:48</b>
Transaction Number	<b>92097075 (CC10010)</b>	Queue Number	<b>657735</b>



Chassis Number	<b>JHMFD16299S408655</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Honda</b>
Model	<b>Civic</b>
Model Year	<b>2009</b>
Color	<b>Grey</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK	حالة المحرك النظري
01.B Mount	CRACKED	كرسي
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Roof Ceiling	LOOSE	بطانه السقف
02.B Sun Visor	LOOSE	حاجب الشمس
02.C Other	GEAR KNOB DAMAGED	اخرى
02.D Odometer reading	NOT CHECK	قراءة عداد المسافات
02.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.F AC Condition	NOT CHECK	المكيف
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES,PORTION FADED,PORTION GETTING RUSTY	الصيغ
03.B Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03.C Floor	UNDER FLOOR RUST PROOFED,PORTION DENT	الارضية
03.D Other	REAR BACK PANEL,SPARE WHEEL	اخرى

DEFECT	REMARKS	
	HOUSING,COMPARTMENT REPAIRED	
03.E Sign of front accident		وجود مؤشر لحادث في المقدمة
03.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
03.G Sign of back accident		وجود مؤشر لحادث في الخلف
<b>04 Engine Cooling System</b>		<b>نظام تبريد المحرك</b>
04.A Radiator Condition	LOWER RADIATOR SUPPORT BEND	حالة المبرد
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Steering Oil	OIL LEAK	زيت المقود
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSH CRACKED	أزرع
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box Mount	CRACKED	كرسي الجير
07.C Visual Gear Box Condition	NOT CHECK & OIL LEAK	حالة الجير النظري
<b>08 Chassis Condition</b>		<b>النشاصي</b>
08.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION KINK & RIGHT SIDE DENT	النشاصيه
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.