



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 22 Nov 2021, 18:02:50 |
| Transaction Number | 49163308 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JTEBU25J785150191 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Toyota |
| Model | Prado |
| Model Year | 2008 |
| Color | White |
| Mileage | 150064 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--|------------------------|
| 01 Body | | جسم المركبة |
| 01.A Fenders | REPAIRED & REPAINTED | مدكار |
| 01.B Paint | TOTALLY REPAINTED , PORTION REPAIRED & DENTS, SCRATCHES ON BODY | الصبغ |
| 01.C Doors | REPAIRED & REPAINTED | أبواب |
| 01.D Bumper | REPAINTED & PORTION DAMAGED | دعامية |
| 01.E Bonnet | REPAIRED & REPAINTED | غطاء المحرك |
| 01.F Roof | REPAIRED & REPAINTED | السقف |
| 01.G Trunk | REPAINTED | صندوق |
| 01.H Rusty | UNDER BODY PARTS, SUSPENSION , CHASSIS FRAME GETTING RUSTY | صدأ |
| 01.I Other | FRONT FENDER FRAME ,BULK HEAD,RADIATOR SUPPORT & LEFT SIDE BODY MOUNT REPAIRED | اخرى |
| 02 Interior Condition | | الحالة الداخلية |
| 02.A AC Condition | OK | المكيف |
| 02.B Mirror | OK | المرآيا |
| 02.C Other | GLASSES COVER LOCK NOT WORKING | اخرى |
| 03 Tires and Rims Condition | | الاطارات |

| DEFECT | REMARKS | |
|----------------------------------|--------------------------|--------------------------|
| 03.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 03.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 03.C Rims Condition | RIMS MINOR SCRATCHES | حالة الجنوط |
| 03.D Spare Tire &Tools | SPARE TYRE COVER MISSING | الاطار الاحتياطي و العدة |
| 04 Engine Condition | | المحرك |
| 04.A Engine Condition | OK | حالة المحرك |
| 05 Chassis Condition | | الشاصي |
| 05.A Chassis | OK | الشاسيه |
| 06 Lights | | الاضاءة |
| 06.A Head Light | OK | الاضاءة الرئيسية |
| 07 Transmission Condition | | الجير |
| 07.A Road Test | NOT CHECK | فحص علي الطريق |
| 07.B Gear Box | OK | الجير |
| 08 Brake Condition | | الفرامل |
| 08.A Disc&Drum | GETTING RUSTY | دسك وطنابير الفرامل |
| 09 Seats Condition | | المقاعد |
| 09.A Seat Condition | OK | حالة المقاعد |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.