

Queue Number 2845060

Transaction Date 07 Oct 2026, 16:14:04

Site Name
840 - Emirates AuctionsTransaction Number
86091693 (CC10026) (CC10026)

Vehicle Details

Chassis Number	MDHAK3CR5K*****
Specification	GCC Specification
Make	Nissan
Model	Micra
Model Year	2019
Color	Red
Mileage	254833 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENTS SCRATCHES	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , LEFT SIDE MISALIGN	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED , MINOR DENT	الارضية
01.F Bumper	MISALIGN , MINOR DENT SCRATCHES	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED , STAY SHOCK WEAK NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	OK	الشاسيه
--------------	----	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	VISUAL OK	الحالة النظرية للمحرك
------------------------------	-----------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGE , EXTRA COVER	حالة المقاعد
---------------------	------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	VISUAL OK	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2024 , RIGHT SIDE 2023 MINOR CUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 , RIGHT SIDE DAMAGE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WATER TANK COVER MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	LEFT SIDE HIGH BEAM NOT WORKING , LENS FADED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INTERIOR PART GETTING RUSTY	اخرى
10.B AC Condition	OK , CONTROL PANEL PORTION WORN OUT	المكيف
10.C Power Window Switch And Glass	REAR RIGHT SIDE ADJUSTABLE LEVER DAMAGE	مفتاح النافذه و الزجاج
10.D Floor Matting	DIRTY	فرش الأرضيه
10.E Dash Board	GLOVE BOX DAMAGE	لوحة القيادة
10.F Roof Ceiling	FABRIC WORN OUT	بطانه السقف
10.G Steering Wheel and control buttons	WORN OUT LOWER PORTION LOOSE COVER MISSING	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae