CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2958558
Transaction Date	09 Nov 2026, 15:52:38
Site Name	840 - Emirates Auctions
Transaction Number	51471780 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WP1ZZZ92ZD*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2013
Color	Black
Mileage	220860 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS MUDDY COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE B/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	REFITTED	صندوق
01.J Door Handle &Lock	FRONT LEFT SIDE HANDLE SENSOR COVER MISSING	مقابض الأبواب والأقفال
01.K Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMLETELY COVERED MUDDY CHECED VISIBLE AREA OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		**المحرك**
03.A Smoke	BLACK	دخان
03.B Other	ENGINE REDUCED POWER WARNING MESSAGED ,	اخري

Condition	Remarks	الحالة
03.C Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY POOR ACCELARATION , DELAY START MAJOR FAULT	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED, NOT CHECKED	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
04.C Four Wheel Drive	NOT CHECKED	الدفع الرباعي
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Hydraulic System	NOT CHECKED	النظام الهيدروليكي
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Audio	REAR BOTH SIDE LCD PANEL PORTION DAMAGED	صوتيات
08.C Dash Board	LEATHER.PORTION LOOSE CRACKED	لوحة القياده
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae