





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20379291	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 09:45:40	Plate Number	: 000556 EA
Queue Number	: 200328	Import Doc. Ref.	:
Chassis Number	: WAUAV94L18D000556	Manufacturer/Model	: AUDI/Q 7
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية TAIL LIGHT BOTH LENS CRACKED//LEFT SIDE HEAD LIGHT NOT WORKING/REAR WIPER ARM BROKEN
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.12 - Transmission Shaft, Flange Or Joint		عمود التعشيق CENTER RUBBER BEARING CRACKED
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية DOT 0117/UNEVEN WEAR/INCOMPLETE TIRE BOLT
05 Body		الهيكل
05.02 - Paint		الصيغ PARTLY DENT/SCRTACHES/FADED
05.04 - Fenders		المدكار FENDER & UNDER COVER MISSING/TOP RADIATOR (PLASTIC) COVER MISSING
05.05 - Bumpers		الدعامية FRONT BUMPER REPAIRED/RADIATOR FRAME CRACKED(PLASTIC)/REAR BUMPER CENTER COMPONENT MISSING
05.06 - Roof		السقف SUN ROOF SWITCH DETACH & DEFECTIVE
05.07 - Floor		الارضية RUNNING BOARD & FLOORING DENT
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT & REAR REPLACED
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب REAR RIGHT WINDOW INDIVIDUAL SWTICH & REAR SUNSHADE & REAR SUN ROOF SWITCH MULFUNCTION
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرايا الجانبية LEFT SIDE MIRROR ADJUSTMENT DEFECTIVE
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها SEAT DAMAGED/MOUNTING MISSING



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20379291	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 09:45:40	Plate Number	: 000556 EA
Queue Number	: 200328	Import Doc. Ref.	:
Chassis Number	: WAUAV94L18D000556	Manufacturer/Model	: AUDI/Q 7
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

	BOLT/ROOF CEILING PARTLY DAMAGED/DRIVER SIDE FLOOR COVER MISSING	
06.14 - Transmission Condition	GEAR TRANSFERCASE OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK/WATER MIX TO ENGINE OIL VISIBLE IN OIL FILLER CAP/SIGN OF REPAIR/ENGINE MIS FIRES	حالة المحرك - الدخان
06.20 - Fuel Tank	FUEL STAIN IN TANK/FUEL LEAK IN ENGINE PIPE	خزان الوقود
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling	LOW COOLING	عطل في المكيف
09.25 - Body Repainted		أثر صبغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		