



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 May 2023, 11:16:41</b>
Transaction Number	<b>77823434 (CC10013)</b>	Queue Number	<b>726280</b>



Chassis Number	<b>JMYLRV73W5J706323</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2005</b>
Color	<b>Gold</b>
Mileage	<b>660726 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Visual Gear Box Condition	NOT CHECK	حالة الجير النظرى
01.B Road Test	NOT CHECK	فحص علي الطريق
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	CRACKED DAMAGED EXPIRED	الاطار الامامي
02.B Rear Tyre	CRACKED DAMAGED EXPIRED	الاطار الخلفي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK	الارضية
03.B Bumper	MISALIGN PORTION CRACK & FADED	دعامية
03.C Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION RUSTY & FADED MINOR DENT SCRATCHES	الصبغ
03.D Windshield	FRONT CRACK	زجاج
03.E Other	VISUAL TEST ONLY	اخرى
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Other	CONSOLE BOX COVER MISSING	اخرى
04.B Mirror	CENTER VIEW MIRROR MISSING	المرايا

DEFECT	REMARKS	
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Indicator & Hazard light	RIGHT SIDE FENDER INDICATOR MISSING	الاشارات
05.B Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
05.C Tail Light	RIGHT SIDE CRACK	الانارة
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK	حالة المحرك النظرى
<b>07 Chassis Condition</b>		<b>النشاصي</b>
07.A Chassis	NOT CHECK	النشاصيه
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Disc&Drum	RUSTY	دسك ووطنابير الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.