



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Sep 2021, 15:43:26
Transaction Number	85472397 (CC10006)	Queue Number	312309



Chassis Number	6T1BE42K57X452818
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Camry
Model Year	2007
Color	White
Mileage	380809 N/A

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	MINOR DENTS & SCRATCHES ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Bumper	REAR CRACKED	دعامية
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Wipers and Arms		المساحات
06.A Other	OK	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل

DEFECT	REMARKS	
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
09.B Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY & BOTH SIDE BUSHES CRACKED	
10 Interior Condition		الاجزاء الداخلية
10.A Other	OK	اخرى
10.B Mirror	OK	المرايا
10.C AC Condition	A/C NOT COOLING	المكيف
11 Tires and Rims Condition		الاطارات
11.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
11.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.