



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18609101	Plate Category	: PRIVATE
Transaction Date	: 25 NOV 2019 11:34:56	Plate Number	: 05468 EA
Queue Number	: 120547	Import Doc. Ref.	:
Chassis Number	: 5N1AR18B27C605468	Manufacturer/Model	: NISSAN/PATHFINDER
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: OTHERS
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots	STEERING BOOT CRACK	وصلات عمود عجلة القيادة
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands	BRAKE TEST NOT DONE / EXHAUST TEST NOT DONE	قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	TIRES DOT 2012 / 2015/ UNEVEN WEAR & CRACK	الاطارات الامامية
04.04 - Rear Left And Right Hand Tires	TIRES DOT 2015 / UNEVEN WEAR & CRACK	الاطارات الخلفية
04.07 - Rims	WHEEL RIM PARTLY RUSTY	الرنجات
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing	INTERIOR PARTLY WORN OUT	المقاعد وحالتها وتثبيتها
06.16 - Engine Condition, Smoke	OIL LEAK FROM ENGINE / ENGINE NOT CRANKING	حالة المحرك - الدخان
06.21 - Battery Condition	WEAK	حالة البطارية
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK / CHASSIS PARTLY RUSTY	الشاسي جيد
09.14 - Sign Of Front Accident	FRONT BULK HEAD REFITTED	أثر حادث في مقدمة المركبة
09.25 - Body Repainted	BODY PORTION PARTLY REPAINTED	أثر صنفغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		