

Queue Number	2822501	Transaction Date	01 Oct 2026, 16:27:31
Site Name	840 - Emirates Auctions	Transaction Number	39064349 (CC10009) (CC10025)



Vehicle Details

Chassis Number	WBAFR1102D*****
Specification	GCC Specification
Make	BMW
Model	530
Model Year	2013
Color	White
Mileage	127391 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.E Bumper	MINOR MISALIGN	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED REFITTED , REAR SWITH NOT WORKING MELTTED	صندوق
01.H Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED, MINOR SHAKING	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	BACK COVER LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED	الحالة النظرية للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 GETTING WORN OUT	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخرى
09 Interior Condition		الحالة الداخليه
09.A Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرآيا
09.B AC Condition	OK , GRILL PORTION DAMAGED	المكيف
09.C Roof Ceiling	PORTION LOOSE	بطانه السقف
09.D Door Panel	PORTION WORN OUT MELTED	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae