

Queue Number 2849328

Transaction Date 13 Oct 2026, 16:18:59

Site Name
840 - Emirates AuctionsTransaction Number
71831588 (CC10013) (CC10025)

Vehicle Details

Chassis Number	1GKS2GKC5H*****
Specification	Imported
Make	GMC
Model	Yukon
Model Year	2017
Color	Maroon
Mileage	248950 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT REPAINTED	الارضية
01.F Bumper	MISALIGN , PART MISSING	دعامية
01.G Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.H Trunk	AUTO NOT WORKING	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FRAME RUST PROOFED MUDDY DIRTY REPAINTED GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	REFITTED , OIL LEAK ,PARTS GETTING RUSTY , MUDDY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Exhaust System نظام العادم

04.A Other	DENT	اخرى
------------	------	------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY (GEAR NOT SHIFTING PROPERLY ELECTRIC ISSUE)	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخرى
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX LEATHER PORTION CRACK PORTION LOOSE ,INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED ELECTRIC ISSUE	اخرى
09.B Mirror	CENTER MIRROR PORTION LOOSE , GETTING FADED	المرآيا
09.C AC Condition	OK	المكيف
09.D Power Window Switch And Glass	RIGHT SIDE BOTH NOT WORKING	مفتاح النافذه و الزجاج
09.E Audio	NOT WORKING	صوتيات
09.F Dash Board	LEATHER REPLACED , PORTION LOOSE	لوحة القيادة
09.G Sun Visor	BOTH SIDE MIRROR LIGHT NOT WORKING	حاجب الشمس
09.H Steering Wheel and control buttons	WORN OUT (HARD) ELECTRIC ISSUE	عجلة القيادة وازرار التحكم
09.I Engine Start Button	STARTING PROBLEM	زر تشغيل المحرك
10 Battery Condition		حالة البطارية
10.A Battery Condition	POSITIVE TERMINAL ELECTRIC BRACKET ISSUE / SOME TIME NOT WORKING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

لشكاوي والمقترحات يمكنك التواصل معنا عبر

