



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Jul 2022, 12:35:36
Transaction Number	15111302 (CC10006)	Queue Number	312309



Chassis Number	5N1AR2MMXDC602052
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Pathfinder
Model Year	2013
Color	Red
Mileage	105185 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02 Body		جسم المركبة
02.A Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
02.B Fenders	FRONT BOTH SIDE PORTION REPAINTED,REFITTED	مدكار
02.C Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصبغ
02.D Pillars	RIGHT SIDE B/PILLAR INNER COVER LOOSE	القوائم
02.E Bonnet	PORTION REPAIRED,REPAINTED,REFITTED	غطاء المحرك
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
03 Interior Condition		الحالة الداخليه
03.A AC Condition	OK	المكيف
03.B Roof Ceiling	PORTION DAMAGED	بطانه السقف
03.C Sun Visor	LOOSE,PORTION DAMAGED	حاجب الشمس
04 Steering Condition		المقود
04.A Steering Oil	OIL LEAK	زيت المقود
04.B Tie Rod End	BOOT CUT	مؤخرة الرودادات

DEFECT	REMARKS	
05 Seats Condition		المقاعد
05.A Seat Belt	FRONT RIGHT SIDE NOT WORKING	حزام الأمان
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
06.C Visual Gear Box Condition	OIL LEAK & REFITTED, JERKING	حالة الجير النظري
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07.B Front Tyre	LEFT SIDE 2020 CRACKED, WORN OUT & RIGHT SIDE 2021	الاطار الامامي
08 Suspension System		ممتص الصدمات
08.A Other	STABILIZER LINK BOOT CUT	اخرى
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
09 Engine Condition		المحرك
09.A Mount	MOUNT BUSH CRACKED	كرسي
09.B Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري
09.C Smoke	MINOR BLACK SMOKE	دخان
10 Chassis Condition		الشاسي
10.A Chassis	FRONT LEFT SIDE CHASSIS LOWER EDGE MINOR DENT, TOO OILY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Transfer Certificate :	66255459
Chassis No :	5N1AR2MMXDC602052
Vehicle Make :	NISSAN
Vehicle Model :	PATHFINDER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Red
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	105190 Kms. x
Origin : United States	Model Year : 2013
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : NIL	Horse : 260
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 2500 Kgs.	Empty : 1946 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17295885		
Inspection Date :	28-07-2022		
Certificate Print Date :	28-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	0 min 55 sec		
Appointment Ref Number :	--		
Start Time :	15:19	End Time :	15:20
Lane :	01	Token No. :	190
Attempt :	2	Prints No. :	1

Inspection Findings

Defects	Issue	Severity
Steering Box repair oil leak	Continuous or excessive oil leak	Major
Tie-rod, Bushes, Center Link replace front right side tie rod end boot	Excessive wear or defective tie-rod, bushes or link	Major
Tire replace front left side tire	Worn out tread tire	Major

Inspection Remarks: Front bumper,bulk head,fender,fender frame repaired old km-293865 on 02-03-2021



Odometer Record

Replace Events Date

28/07/2022

Payment Details

Inspection Performed by 30544	Payment Method Cash	Transaction Number 17295885	Service Fees AED 70 Collected on 28/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

