

Queue Number 2866287

Transaction Date 14 Oct 2026, 12:55:23

Site Name
840 - Emirates AuctionsTransaction Number
71072654 (CC10026) (CC10026)

Vehicle Details

Chassis Number	SCBBE53W47*****
Specification	GCC Specification
Make	Bentley
Model	-
Model Year	2007
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED , REFFITED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY , SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR PARTS DENT , MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Bonnet	REFITTED , STAY SHOCK WEAK NOT WORKING	غطاء المحرك
01.H Vehicle Model	CONTINENTAL	طرارز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION COVER , CHECK VISIBLE AREA ONLY , OILLY MUDDY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK	حالة المقاعد
---------------------	---------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECK , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2024 & RIGHT SIDE 2019 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2022 EXPIRED & RIGHT SIDE 2019 CRACK EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT CHECK	المكيف
09.C Audio	DISPLAY LCD SCREEN PORTION FADED	صوتيات
09.D Roof Ceiling	PORTION LOOSE	بطانة السقف
09.E Odometer reading	NOT CHECK	قراءة عداد المسافات
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
09.H Engine Start Button	FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae