

Queue Number 2856303

Transaction Date 12 Oct 2026, 16:47:19

Site Name
840 - Emirates AuctionsTransaction Number
58229733 (CC10013) (CC10025)

Vehicle Details

Chassis Number	WDDNG7BB1B*****
Specification	Imported
Make	Mercedes
Model	S 550
Model Year	2011
Color	White
Mileage	314137 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCH	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED REINFORCEMENT DENTS	الارضية
01.F Bumper	PORTION DAMAGED LOOSE , GRILL PORTION LOOSE	دعامية
01.G Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.H Other	FRONT ASSEMBLY REFITTED	اخرى
01.I Sign of front accident		وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT PORTION CUT	حالة المقاعد
---------------------	-------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE MINOR CRACK	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.C Fog light	NOT WORKING	كشف الضباب
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION PARTS REFITTED	اخرى
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Boot	BOOT WORN OUT / LEAK	ربلة المقود
09.B Tie Rod End	BOOT CUT	مؤخرة الروداد
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,CENTER CONSOLE BOX LEATHER PORTION LOOSE LOCK COVER PORTION DAMAGED , REAR LOCK DAMAGED	اخرى
10.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY , LIGHT COVER PORTION CRACK	المرآيا
10.C AC Condition	OK	المكيف
10.D Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.E Engine Start Button	STARTING PROBLEM	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae