



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19845876	Plate Category	: PRIVATE
Transaction Date	: 27 MAY 2020 15:15:49	Plate Number	: 05279 EA
Queue Number	: 179548	Import Doc. Ref.	:
Chassis Number	: MNTBC2C99F6005279	Manufacturer/Model	: NISSAN/TIIDA
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.02 - Paint		الصبغ
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
09 Auction		الفحص الكامل
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Test Certificate



PASS

Plate Details :	--
Chassis No :	MNTBC2C99F6005279
Vehicle Make :	NISSAN
Vehicle Model :	TIIDA
Vehicle Class :	Light Vehicle
Body Type :	HATCHBACK
Fuel :	Benzene
Color :	Silver
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	89157 Kms.
Origin : Thailand	Model Year : 2015
Gear Type : Automatic	
Engine No : HR16942601B	Engine Size : 1600 CC
Axles No : 2	Horse Power : --
No Of Doors : 5	
G. V. W. : 1500 Kgs.	Cylinders : 4
	No Of Seats : 5
	Empty Weight : 1000 Kgs.

Certificate Number :	5-TAS-2020-12003662
Inspection Date :	02-06-2020
Certificate Print Date :	02-06-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	2 min 14 sec
Appointment Ref Number : --	
Start Time : 15:40	End Time : 15:42
Lane : 01	Token No. : 7
Attempt : 2	Prints No. : 1

Carbon footprint



1.4 ton

ton CO2



8183 KM
Distance per
year



582 L
Fuel consumed
per year



943 AED
Fuel cost per
year



1.4 ton
Carbon footprint
per year

Thank you! You are environment protector

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Doors and Locks Incorrect Number of doors (does not require doc)	5	4	

Inspection Remarks: REAR COMPARTMENT & DOOR PILLAR REPAIRED//REAR BOTH SIDE CHASSIS REPAIRED CCM OK W.O# 20200601-003

Payment Details

Inspection Performed by 62403	Payment Method VTP Credit Account	Transaction Number 12003662	Service Fees AED 70 Collected on 02/06/2020
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Gilbert De Guzman Balatero

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

