

Queue Number

2827772

Transaction Date

03 Oct 2026, 13:01:15

Site Name

840 - Emirates Auctions

Transaction Number

42345721 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1GYS47KJXF*****
Specification	GCC Specification
Make	Cadillac
Model	Escalade
Model Year	2015
Color	--
Mileage	377437 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REAPINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES , PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH ABNORMAL SOUND WHEN OPENNING FROM STEPPING BOARD SENSOR / NOT WORKING	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DIRTY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE , PART MISSING	دعامية
01.G Bonnet	REPAINTED,REFITTED , MISALIGN	غطاء المحرك
01.H Door Handle &Lock	FRONT LEFT SIDE OUTER LOCK COVER MISSING	مقابض الأبواب والأقفال
01.I Vehicle Color	BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME RUST PROOFED GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK WORN OUT	حالة المقاعد
---------------------	------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Fog light	RIGHT SIDE LOOSE	كشف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09.B Axle	BOOT CUT	اكسلات
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER LEATHER LOOSE , INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	FRONT OK / REAR PANEL PART MISSING NOT WORKING PROPERLY	المكيف
10.C Floor Matting	EXTRA COVER	فرش الأرضية
10.D Dash Board	PORTION WORN OUT	لوحة القيادة
10.E Roof Ceiling	MIDDLE LCD LOCK DAMAGED	بطانة السقف
10.F Sun Visor	RIGHT SIDE GLASS MIRROR COVER MISSING	حاجب الشمس
10.G Door Panel	LEATHER LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae