CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2933993
Transaction Date	02 Nov 2026, 15:06:48
Site Name	840 - Emirates Auctions
Transaction Number	10195986 (CC10010) (CC10010)



Vehicle Details

Chassis Number	LFPH4BCP9J*******
Specification	Imported
Make	HONGQI
Model	CA7201A
Model Year	2018
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED PORTION RPAIRED,MINOR DENTS SCRATCHES .	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN ,SCRATCHES .	دعامية
01.E Door Handle &Lock	BOTH SIDE OUTER HANDLE STRIP MISSING.	مقابض الأبواب والأقفال
01.F Sign of side accident	QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
01.G Vehicle Color	SILVER /BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 DRY CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
09.B AC Condition	NOT CHECKED .	المكيف
09.C Roof Ceiling	PORTION LOOSE.	بطانه السقف
09.D Odometer reading	NOT CHECKED ,	قراءة عداد المسافات
09.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.F Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات
09.G Engine Start Button	IGNITION SYSTEM NOT WORKING ,	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae