



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20219433	Plate Category	: PRIVATE
Transaction Date	: 12 JUL 2020 12:34:40	Plate Number	: 253809 EA
Queue Number	: 195073	Import Doc. Ref.	:
Chassis Number	: JTDBR23E560253809	Manufacturer/Model	: TOYOTA/COROLLA
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2017 الاطارات الامامية
04.08 - Spare Tires		SPARE TIRE RUBBER MISSING الاطار الاحتياطي
05 Body		الهيكل
05.02 - Paint		BODY SCRATCH & DENT الصبغ
05.07 - Floor		REAR COMPARTMENT REPAIRED الارضية
05.08 - Chassis (Frame)		REAR BOTH SIDE & FRONT LEFT SIDE FRAME MEMBER END DENT الشاصية
05.12 - Side Safety Frame		BULKHEAD /RADIATOR SUPPORT FRAME & BUMPER SUPPORT REPAIRED الواقيات الجانبية
06 General Items		الاشياء العامة
06.08 - Interior Lights		INTERIOR DIRTY الانوار الداخلية
06.16 - Engine Condition, Smoke		ENGINE & GEAR OIL STAIN حالة المحرك - الدخان
06.21 - Battery Condition		BATTERY WEAK حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		91796 KM CAR WAS USED BY DRIVING SCHOOL ملاحظات اخرى
09 Auction		الفحص الكامل
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.25 - Body Repainted		BODY PORTION REPAINTED أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.