

Queue Number

2673736

Transaction Date

25 Aug 2026, 10:42:19

Site Name

840 - Emirates Auctions

Transaction Number

46948085 (CC10008) (CC10008)



Vehicle Details

Chassis Number	KNDMA5C10G*****
Specification	Imported
Make	Kia
Model	Sedona
Model Year	2016
Color	Silver
Mileage	137401 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE ,REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.C Doors	LEFT SIDE BOTH DOOR REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	PORTION DENT	الارضية
01.F Bumper	MISALIGN ,FIXED BY SCREW	دعامية
01.G Bonnet	REPAINTED	غطاء المحرك
01.H Fuel Tank	DENT	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE LOADING POINT AREA DENT / EDGE BEND / PORTION GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Other	ENGINE UPPER COVER LOOSE DAMAGE,ALTERNATOR NOT CHARGING	اخرى
03.B Engine Visual Condition	OIL LEAK ,REFITTED ,RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED ,RUSTY ,NOT WORKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACK EXPIRE	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2023 RIGHT SIDE 2021 CRACK EXPIRE	الاطار الخلفي
07 Lights		الاضاءة
07.A Other	CAR HAVE ELECTRIC ISSUE	اخرى
07.B Warning Light	WARNING LIGHT SHOW IN DISPLAY	ضوء تحذير
07.C Fog light	NOT WORKING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طنايبير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS RUSTY ,WATER FLOODED ,CENTER CONSOLE BOX DAMAGED	اخرى
11.B AC Condition	NOT WORKING	المكيف
11.C Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.D Steering Wheel and control buttons	WORN OUT,RE LEATHER	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae