

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 46077577 (CC10010) Transaction Date

08 Mar 2023, 12:05:06

Queue Number

684971



Chassis Number JM7BK326X91466344

Engine Number

Vehicle Class Car

Manufacturer Mazda

Model 3

Model Year 2009

Color --

Mileage **001 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

سم المركبة		O1 Body
<u>-</u> ري	VISUAL TEST ONLY.	01.A Other
درضية	UNDER BODY, SUSPENSION PARTS, CHASSIS NOT CHECKED	01.B Floor
	•	
عامية	MISALIGN.	01.C Bumper
ون المركبة	WHITE.	01.D Vehicle Color
<u>صبغ</u>	PAINT NOT CHECKED ,DENTS SCRATCHES ,PAINT FADED ,BODY RUSTY ,,DUSTY.	01.E Paint
شاصي		02 Chassis Condition
شاسيه	NOT CHECKED.	02.A Chassis
قم القاعدة	VIN NUMBER CHECKED ONLY ,VIN STICKER ,FIREWALL.	02.B Chassis Number
لاطارات		03 Tires and Rims Condition
دطار الامامي	CRACKED,	03.A Front Tyre
دطار الخلفي	CRACKED	03.B Rear Tyre
حاله الداخليه		04 Interior Condition
راءة عداد المسافات	NOT CHECKED.	04.A Odometer reading
جلة القيادة وازرار التحكم	WORN OUT .	04.B Steering Wheel and

DEFECT	REMARKS	
control buttons		
04.C AC Condition	NOT CHECKED.	المكيف
04.D Other	WORN OUT.	اخري
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	NOT CHECKED.	حالة الجير النظرى
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED ,KEY MISSING .	حالة المحرك النظرى
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.